





PARTS BOOK


HD 8-26


HD 8-32


Industrial automatic heavy duty sewing
machine with unison feed


HD
texi



































9332 844395












9332 844365
















	
9332 824895	9332 824885


















0119 132898




0795 798332



0795 798332



0795 798332




9332 504709


0289 938799


0795 79982


0209 799999


0286 994995

















0857 510101

